




COMPARTMENTS WHERE FITTINGS ARE NOT
SHOWN ARE AS ON AS FITTED ARRGT.
PLANS "H.M.A.S. GEELONG.


FORECASTLE DECK

UPPER DECK.

2 POR. GUN FITTED, 4" H.A.Q.F. TO BE FITTED LATER
AND TO REPLACE 12 POR. GUN.



FORECASTLE DECK.




PLAN OF BRIDGE CANOPY TOP.

UPPER DECK.

H.M.A.S. "SHEPPARTON"
GENERAL ARRANGEMENT
[AS FITTED]
LOWER DECK & HOLD





SCALE 4'-0"

COMPARTMENTS WHERE FITTINGS ARE NOT
SHOWN ARE AS ON AS FITTED AS AT
PLANS H.M.A.S. GEELONG




LOWER DECK.

HOLD



LOWER DECK.




H.M.A.S. "SHEPPARTON"

SURVEY & CHART ROOM - AFT SUPERSTRUCTURE X

CONSTRUCTION DETAILS

SCALE: $\frac{1}{2}$ " = 1 FOOT

ALTERATIONS SHOWN THUS []



LETTER NO	DATED	FILE NO
-----------	-------	---------

A & A ITEM NO JOB NO

2480 DIAGRAM

D.N.C. PLAN.

WEIGHT OF ITEM

WEIGHT ADDED TO VESSEL

WEIGHT SURRENDERED

TOTAL WEIGHT ADDED SURRENDERED


HEIGHT ABOVE BASE LINE

HEIGHT ABOVE BASE LINE

HEIGHT ABOVE BASE LINE

RELEVANT OR REFERENCE PLANS

PLAN AT UPPER DK.



EXTRACT FROM S.M.A.G.I'S LETTER DATED 26/11/53


"The old weather deck timber has been completely removed, including the boundary angle. New coamings and boundary angles were fitted to the deck house to prevent a recurrence of the corrosion. The deck plating has been cleaned and covered with coatings."

FILE 4284/29/53, "Report of Survey of Hull Structure" refers.

False decking removed.

See also GMG.I Letter 2339


16/3/54. (4284-29-40) which officially confirms the above alteration



ELEVATION OF STARBOARD BULKHEAD "A"


LOOKING TO PORT.

PORT BULKHEAD SIMILAR.



BULKHEAD "B"


LOOKING AFT.



PLAN AT FORECASTLE DK.

10/18
0162796
27/11/53

KOTH E HARPER.



TYPICAL SECTION AT "X-X"

LOOKING AFT.